# Lab Activity 3
Creating Displays and Adding Graphic Objects

1. Open your "Swagelok_PLC_Trainer" application in FactoryTalkView Studio – View Machine Edition

2. Add the appropriate pushbuttons and display indicators to the IO Screen display and Conveyor display as shown below. Select only images (or use the Symbol Indicator for case of the motor) that can show the object in two states or colors. Note for the conveyor display, the text below each pushbutton/indicator is the tag name for the connection.

Lab Activity 3
Creating Displays and Adding Graphic Objects

3. For the Conveyor Display, add 4 Multistate Indicators to display the boxes corresponding to the tags listed. Also add Numeric Input Enable pushbuttons to adjust the conveyor shutdown time delay and the number of parts to count before shutting down.