Activity 1 - Uploading Project without Project File

Friday, December 27, 2019 2:20 PM

1. Configure communication hardware
   a. Setup Network Adapter - Ethernet IP Setup
   b. Open RSLinx & setup drivers









2. Open Studio 5000

3. Select PLC and press upload:


Upload From Controller or Terminal
Communication software:
RSLinx Classic
Autobrowse
Refresh
Workstation, LAPTOP-K13QEISJ
Linx Gateways, Ethernet
AB_DF1-1, DH-485
AB_ETHIP-1, Ethernet
192.168.1.200, PanelView Plus 7 Standard 700, PanelView Plus_7 Standard 700
192.168.1.40, 1769-L16ER-BB1B LOGIX5316ER, 1769-L16ER/B LOGIX5316ER
192.168.1.53, FactoryTalk Linx - Desktop, LAPTOP-K13QEISJ
EMU500-1, DH-485
Version: 30.00
Upload
Cancel


Connected To Upload
Options
General
Date/Time
Major Faults
Minor Faults
Nonvolatile Memory
Condition: The project file 'Swagelok_Trainers.ACD' was not found in your project directory. Select new or existing project file.
Connected Controller:
Controller Name: Swagelok_Trainers
Controller Type: 1769-L16ER/B CompactLogix™ 5370 Controller
Comm Path: AB_ETHIP-1\192.168.1.40
Serial Number: 60E16165
Security: No Protection
Offline Project:
Controller Name:
Controller Type:
File:
Serial Number:
Security:
Select File...
Cancel
Help

Navigate to desired folder:



Specify a name for a NEW Project File and press "SELECT":