
## Lab Activity 2 Creating Displays and Adding Graphic Objects


- 1. Open your "Swagelok\_PLC\_Trainer" application in FactoryTalkView Studio View Machine Edition
- 2. Add display navigation as shown below:




RETURN TO MAIN

## Lab Activity 2

Creating Displays and Adding Graphic Objects



| 10 Screen - /Swagelok Trainer HMI on UA V1// (Display) |                             |  |
|--|-----------------------------|--|
| Return<br>to Main                                      | Swagelok                    |  |
| LIGHT STATUS INDICATORS                                |                             |  |
| RED LT   | YLWLT<br>ON GRN LT<br>ON ON |  |
| Press Buttons Below to Turn ON Light                   |                             |  |
| Push   | Fush Push Push              |  |
|  |                             |  |
|  |                             |  |



3. Add an On Top display similar to the below image. Add navigation to get to the On Top display to the Main Display. Make the Close button blink.

